oss of HTA power RTH (TVC)

pen

[f TVC gets too cold:
]) No video

2) No PTU control
Worst Case:

No PTU control of elbow camera which prevents arm stowage.

## **OESIGN FEATURES**

The N11 RVS/PTU cable is a 15-inch long assembly, 16-wire assembly. The cable is terminated on each end with a 37-pin connector (PI, KJG6E14N35SNI6). The video and sync wires are shielded #24 Twinax twisted-pair wires. The N11 cable provides power and commands from the remote video switch (NVS) to the RMS elbow camera stack and returns video signals to the RVS.

The cable design is taken from the successfully flown Apollo program. The design is a cable-connector assembly in which the wire terminations are protected from excessive flexture at the joint between the wire and the connector terminat. The load concentration is moved away from the conductor connection and distributed axially along the length of the conductors encapsulated in a potted-taper profile. This technique also protects the assembly from dirt and entrapped moisture which could cause problems in space.

The cable and its components meet the applicable requirements of NASA, Military and RCA specifications. These requirements include:

- General/Mechanical/Electrical Features
- Design and Construction
- Materials
- Terminal Solderability
- Environmental
- Qualification
- Marking and Serialization
- Traceability and Documentation

REVISED 5-7-87

FMEA NO. W 11.10 CRITICALITY 2/1R		SHUTTLE CCTV CRITICAL ITEMS LEST	DNLT Cable DNG NOT 2293995-502 1550E0 10-14-86 SHEET 2 0F 5
FATEURE MODE AND CAUSE	FAILURE EFFECT	CRITICAL ITEMS LIST ISSUED 10-14-86	
en (TVC)	If TVC gets too cold:  1) No video 2) No PTU control  Norst Case:  No PTU control of elbow camera which prevents arm stowage.		

FMEA NO. W 11.10 CRITICALITY 2/NR		SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT CALTE UNG NO. 2293595-502 USSUED TO-14-06 SHEET 3 OF 5	
FATCURE MODE AND CAUSE	FAILURE EFFECT ON END LITEM	RATIONALE FOR ACCEPTANCE	RATIONALE FOR ACCEPTANCE	
ss of HTR power RTN (TVC)	If TVC gets too cold:  1) No video 2) No PIU control  Worst Case:  No PIU control of elbow camera which prevents arm stowage.	Procurement Control - Wire, connectors, solder, etc. are procured from approved ver and suppliers which meet the requirements set forth in the CCTV contract and Quality Plan Work Statement (WS-2593176).  Incoming Inspection & Storage - Incoming Quality inspections are made on all receiving inspections and parts. Results are recorded by lot and retained in file by drawing a control numbers for future reference and traceability. Accepted items are delivere Material Controlled Stores and retained under specified conditions until cable fabrication is required. Mon-conforming materials are held for Material Review Bod (MRB) disposition. [PAI-307, PAI IQC-53].  Assembly & Test - Prior to the start of assembly, all items are verified to be correctly stock room personnel as the items are accumulated to form a kit. The items are verified again by the operator who assembles the kit by checking against the as-built-parts-list (ABPL).  Instructions are given in assembly drawing notes and applicable documents. These allowed in-line splitling of standard interconnecting wire using Raychem solder she will be applied to process Standard in-line splitling of standard interconnecting wire using Raychem solders is 2280876 - Process Standard marking of parts or assemblies with epoxy colors, 22808. Potting naterial and test procedure (TP-AI-2293287). Quality and DCAS Inspections performed at the completion of key operations.  Preparation for Shipment - When fabrication and test is complete, the cable assembly packaged according to 2280746, Process Standard for Packaging and Handling Guidelin All related documentation including assembly drawings, Parts List, AHPL, Test Data, is gathered and held in a documentation folder assigned specifically to each cable assembly. This folder is retained for reference.		

REVISED 5-7-87

<del></del>				
FNEA NO. W 11.10  CRITICALITY 2/18		SHUTTLE COTV CRITICAL ITEMS LIST	URIT Cable ONG NO. 229395-502 ISSUED 10-14-86 SHEET 4 OF 5	
FAILURE MODE AND CAUSE	FATLURE EFFECT ON END ITEM	RAFIONALE FOR ACCEPTANCE		
FAILURE MODE AND CAUSE ss of HTR power ATN (TVC) en	FAILURE EFFECT ON END ITEM  If TYC gets too cold: 1) No video from wrist camera stack 2) No video or control from elbow camera stack  Worst Case: No PTU control of elbow camera which prevents arm stowage.	RATIONALE FOR ACCEPTANCE  FAILURE HISTORY  There have been no reported failures during RCA testing	, pre-flight ar flight.	
	ł	1		

FMEA NO. W 11.10 CRITICALITY 2/1R		SHUTTLE CETY CRITICAL ITEMS LIST	UNTT CASTE DNG NO. 2293995-502 ISSUED 10-14-86 SHEET 5 OF 5
FAILURE MODE AND CAUSE	FATURE EFFECT ON END LIEM	RATIONALE FOR ACCEPTANCE	
ss of HTR power RTM (TVC)	If TVN gets too cold: 1) No video from wrist camera stack 2) No video or control from elbow camera stack Worst Case: No PTU control of elbow camera which prevents arm stowage.	OPERATIONAL EFFECTS  Loss of ability to position the Elbow camera. Possite allow camera physically interferes with a payload. I payload. I payload bay door cannot be closed. Loss of crew and CREW ACTIONS  Perform EVA to reposition the albow camera, use RMS rejettison the RMS.  CREW TRAINING  Crew should be trained in contingency EVA and RMS open MISSION CONSTRAINT  Do not manifest albow camera for any flight where the interfere with each other (for any pan or tilt angle not change the camera position until the interfering	If RMS cannot be stowed the port vehicle.  Butlon to reposition the camera, or erations procedures.  E payload and the elbow camera can local the camera must be flown do